


**TYPICAL BUILT-IN
CABINET DETAIL**



	<p>Project Title: REPAIR OF DA-PRDP PSO VISAYAS CLUSTER OFFICE (ILOILO) LOCATION: ILOILO SPORTS COMPLEX, LAPAZ ILOILO CITY</p>	<p>Prepared By: ENGR. ANTONIO RONEL T. TRINO I-BUILD COMPONENT HEAD</p>	<p>Noted By: ENGR. JOSE ALBERT A. BARROGO DEPUTY PROJECT DIRECTOR</p>	<p>Approved By: ENGR. REMELYN R. RECOTER MNSA, CESO-III PROJECT DIRECTOR</p>	<p>Sheet No. 5/10</p>
--	---	--	--	---	----------------------------------